

SONY®



SAR Information
FCC Statement
Declaration of Conformity

G3226

Important Information

United States & Canada

THIS PHONE MODEL HAS BEEN CERTIFIED IN COMPLIANCE WITH THE GOVERNMENT'S REQUIREMENTS FOR EXPOSURE TO RADIO WAVES.

The G3226 mobile phone has been designed to comply with the applicable safety requirements for exposure to radio waves. Your wireless phone is a radio transmitter and receiver. It is designed to not exceed the limits of exposure to radio frequency (RF) energy set by governmental authorities. These limits establish permitted levels of RF energy exposure for the general population. The guidelines are based on standards that were developed by international scientific organizations through periodic and thorough evaluation in scientific studies. The standards include a safety margin designed to assure the safety of all individuals, regardless of age and health.

The radio wave exposure guidelines employ a unit of measurement known as the Specific Absorption Rate (SAR). Tests for SAR are conducted using standardised methods with the phone transmitting at its highest certified power level in all used frequency bands. While there may be differences between the SAR levels of various phone models, they are all designed to meet the relevant guidelines for exposure to radio waves.

The highest SAR value as reported to the authorities for this phone model when tested for use by the ear is 1.11 W/kg and when worn on the body is 0.5 W/kg and for WiFi hotspot mode is 1.18 W/kg. For body-worn operation, the phone has been tested when positioned a minimum of 15 mm from the body without any metal parts in the vicinity of the phone or when properly used with an appropriate accessory and worn on the body. For devices which include "WiFi hotspot" functionality, SAR measurements for the device operating in WiFi hotspot mode were taken using a separation distance of 10 mm. Use of third-party accessories may result in different SAR levels than those reported.

Before a phone model is available for sale to the public in the US, it must be tested and certified by the Federal Communications Commission (FCC) that it does not exceed the limit established by the government-adopted requirement for safe exposure. The tests are performed in positions and locations (i.e., by the ear and worn on the body) as required by the FCC for each model. The FCC has granted an Equipment

Authorization for this phone model with all reported SAR levels evaluated as in compliance with the FCC RF exposure guidelines. While there may be differences between the SAR levels of various phones, all mobile phones granted an FCC equipment authorization meet the government requirement for safe exposure. SAR information on this phone model is on file at the FCC and can be found under the Display Grant section of <http://transition.fcc.gov/oet/ea/fccid/> after searching on FCC ID PY7-10710W. Additional information on SAR can be found on the Mobile Manufacturers Forum EMF website at <http://www.emfexplained.info/>.

** In the United States, the SAR limit for mobile phones used by the public is 1.6 watts/kilogram (W/kg) averaged over one gram of tissue. The standard incorporates a margin of safety to give additional protection for the public and to account for any variations in measurements.*



| | | |
|-----------------------------|---|---|
| Anguilla | 1-800-080-9518 (Toll Free) | questions.CO@support.sonymobile.com |
| Antigua and Barbuda | 1-800-081-9518 (Toll Free) | questions.CO@support.sonymobile.com |
| Argentina | 0800-333-7427 (09:00 a 20:00, Toll Free) | questions.com@support.sonymobile.com Servicio Oficial Multipoint: Av. Corrientes 654, Buenos Aires, Capital Federal. |
| Australia | 1300 650-050 (Toll Free) | questions.AU@support.sonymobile.com |
| The Bahamas | 1-800-205-6062 (Toll Free) | questions.CO@support.sonymobile.com |
| Barbados | 1-800-082-9518 (Toll Free) | questions.CO@support.sonymobile.com |
| Belgique/ België | 02-0745 1611 | questions.BE@support.sonymobile.com |
| Belize | AN 815, PIN 5597 (Toll Free) | questions.CO@support.sonymobile.com |
| Bermuda | 1-800-083-9518 (Toll Free) | questions.CO@support.sonymobile.com |
| Bolivia | 800-100-542 (número gratuito) | questions.CO@support.sonymobile.com |
| Brasil | 4001-0444 (Capitais e regiões metropolitanas) 0800 884 0444 (Demais regiões) | questions.BR@support.sonymobile.com |
| Canada | 1 866 766 9374 (Toll Free / sans frais) | questions.CA@support.sonymobile.com |
| Cayman Islands | 1-800-084-9518 (Toll Free) | questions.CO@support.sonymobile.com |
| Central and Southern Africa | +27 11 506 0123 | questions.CF@support.sonymobile.com |
| Česká republika | 844 550 055 (Za tarif místního volání) | questions.CZ@support.sonymobile.com |

| | | |
|-------------|---|-------------------------------------|
| Chile | 800-646-425 (número gratuito) | questions.CO@support.sonymobile.com |
| Colombia | 01800-0966-080 (número gratuito) | questions.CO@support.sonymobile.com |
| Costa Rica | 0 800 011 0400 (número gratuito) | questions.CO@support.sonymobile.com |
| Danmark | 3331 2828 | questions.DK@support.sonymobile.com |
| Deutschland | 0211 993 342020 (Anruf in das deutsche Festnetz, Kosten variieren je nach Anbieter) | questions.DE@support.sonymobile.com |
| Dominica | 1-800-085-9518 (Toll Free) | questions.CO@support.sonymobile.com |
| Ecuador | 1-800-0102-50 (número gratuito) | questions.CO@support.sonymobile.com |
| Eesti | 06 032 032 | questions.EE@support.sonymobile.com |
| Egypt/مصر | 16727 | questions.EG@support.sonymobile.com |
| Ελλάδα | 801 11 810 810 +30 210 899 19 19 (από κινητό τηλέφωνο) | questions.GR@support.sonymobile.com |
| El Salvador | 800-6323 (número gratuito) | questions.CO@support.sonymobile.com |
| España | 902 180 576 (tarifa local) | questions.ES@support.sonymobile.com |
| France | 09 69 32 21 21 09 69 32 21 22 (Xperia™ uniquement) | questions.FR@support.sonymobile.com |
| Guatemala | 1-800-300-0057 (número gratuito) | questions.CO@support.sonymobile.com |
| Haiti/Ayiti | AN 193, PIN 5598 (numéro gratuit / nimewo gratis) | questions.CO@support.sonymobile.com |
| Honduras | AN 8000122, PIN 5599 (número gratuito) | questions.CO@support.sonymobile.com |

| | | |
|-------------------------|---|-------------------------------------|
| Hong Kong/ 香港 | +852 8203 8863 | questions.HK@support.sonymobile.com |
| Hrvatska | +385 (0) 72 000 000 | questions.HR@support.sonymobile.com |
| India/भारत | 1800 103 7799 (Toll Free) | questions.IN@support.sonymobile.com |
| Indonesia | +62 21 2935 7669 | questions.ID@support.sonymobile.com |
| Ireland | 1850 545 888 (Local rate) | questions.IE@support.sonymobile.com |
| Italia | 06 48895206 (tariffa locale) | questions.IT@support.sonymobile.com |
| Jamaica | 1-800-442-3471 (Toll Free) | questions.CO@support.sonymobile.com |
| Κύπρος/ Κίβρις | 0800 90 909 | questions.CY@support.sonymobile.com |
| Latvija | 67 21 43 01 | questions.LV@support.sonymobile.com |
| Lietuva | 8 700 55030 | questions.LT@support.sonymobile.com |
| Magyarország | 06 (1) 8 700 100 | questions.HU@support.sonymobile.com |
| Malaysia | 1 800-88-7666 | questions.MY@support.sonymobile.com |
| Maroc/المغرب | +212 2 2958 344 | questions.MA@support.sonymobile.com |
| México | 0 1800 000 4722 (número gratuito) | questions.MX@support.sonymobile.com |
| Nederland | 0900 8998318 | questions.NL@support.sonymobile.com |
| Nederlandse Antillen | 001-866-509-8660 (gratis nummer) | questions.CO@support.sonymobile.com |
| New Zealand | 0800-100-150 (Toll Free) | questions.NZ@support.sonymobile.com |
| Nicaragua | AN 1800-0166, PIN 5600 (número gratuito) | questions.CO@support.sonymobile.com |
| Norge | 815 00 840 (lokaltakst) | questions.NO@support.sonymobile.com |
| Österreich | 0810 200 245 (Anruf in das Festnetz, Kosten variieren je nach Anbieter) | questions.AT@support.sonymobile.com |
| Pakistan/ پاکستان | 021 - 111 22 55 73 | questions.PK@support.sonymobile.com |

| | | |
|--|--|--------------------------------------|
| Panamá | 00800-787-0009 (número gratuito) | questions.CO@support.sonymobile.com |
| Paraguay | 009 800 54 20032 (número gratuito) | questions.CO@support.sonymobile.com |
| Perú | 0800-532-38 (número gratuito) | questions.CO@support.sonymobile.com |
| Philippines/ Pilipinas | +632 479 9777 or 1800 1 853 7669 | questions.PH@support.sonymobile.com |
| Polska | +48 22 22 77 444 | questions.PL@support.sonymobile.com |
| Portugal | 808 204 466 (chamada local) | questions.PT@support.sonymobile.com |
| República Dominicana | 1-800-751-3370 (número gratuito) | questions.CO@support.sonymobile.com |
| România | +40 371 062 222 | questions.RO@support.sonymobile.com |
| Saint Kitts and Nevis | 1-800-087-9518 (Toll Free) | questions.CO@support.sonymobile.com |
| Saint Vincent and the Grenadines | 1-800-088-9518 (Toll Free) | questions.CO@support.sonymobile.com |
| Schweiz/ Suisse/ Svizzera | 0848 824 040 (Anruf in das Festnetz, Kosten variieren je nach Anbieter/ Tarif local) | questions.CH@support.sonymobile .com |
| Singapore | +65 6744 0733 | questions.SG@support.sonymobile.com |
| Slovenia | 0800 81291 (Strošek lokalnega klica) | questions.si@support.sonymobile.com |
| Slovensko | 02 5443 6443 | questions.SK@support.sonymobile.com |
| South Africa | 0861 632222 | questions.ZA@support.sonymobile.com |
| South Korea/ 대한민국 | (+82) 1588 4170 | questions.KO@support.sonymobile.com |
| Suomi | | questions.FI@support.sonymobile.com |
| Sverige | 013 24 45 00 (lokal taxa) | questions.SE@support.sonymobile.com |
| Thailand | 001 800 852 7663 or 02401 3030 | questions.CO@support.sonymobile.com |

| | | |
|--------------------------------|--|---|
| Trinidad and Tobago | 1-800-080-9521 (Toll Free) | questions.CO@support.sonymobile.com |
| Türkiye | +90 212 473 77 77 | questions.TR@support.sonymobile.com |
| United Kingdom | 0370-5237237 (Local rate) | questions.GB@support.sonymobile.com |
| United States | 1 866 766 9374 | questions.US@support.sonymobile.com |
| Uruguay | 000-401-787-013 (09:00 a 20:00, Toll Free) | questions.com@support.sonymobile.com Servicio Oficial A-Novo Uruguay S.A.: Mercedes 935, Montevideo. |
| Venezuela | 0-800-1-00-2250 (número gratuito) | questions.CO@support.sonymobile.com |
| Việt Nam | 1900 1525 (miễn phí) | questions.VN@support.sonymobile.com |
| България | 0800 1 8778 | questions.BG@support.sonymobile.com |
| Россия | 8-800-1008022 | questions.RU@support.sonymobile.com |
| Україна | +38 044 590 1515 | questions.UA@support.sonymobile.com |
| الأردن | +971 4 3919 880 | questions.JO@support.sonymobile.com |
| الإمارات العربية المتحدة (UAE) | +971 4 3919 880 | questions.AE@support.sonymobile.com |
| الكويت | +971 4 3919 880 | questions.KW@support.sonymobile.com |
| المملكة العربية السعودية | 800-8200-727 | questions.SA@support.sonymobile.com |
| 中国 | +86 400 810 0000 | questions.CN@sonymobile.com |
| 台灣 | +886 2 25625511 | questions.TW@support.sonymobile.com |
| ไทย | 02 2483 030 | questions.TH@support.sonymobile.com |

FCC Statement

This device complies with Part 15 of the FCC rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.

Any change or modification not expressly approved by Sony may void the user's authority to operate the equipment.

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation.

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

www.sonymobile.com

SONY®

Sony Mobile Communications Inc.
4-12-3 Higashi-Shinagawa, Shinagawa-ku, Tokyo, 140-0002
Japan