

WINDSOR



MAINTENANCE

86372330

COMMODORE 20




01) Drain solution tank.




02) Drain recovery tank.



03) Rinse out and clean recovery tank.



04) Clean mesh water filter and water filter cap.



05) Clean float shut off.



06) Remove jets and soak in a solution of hot water and vinegar overnight.




07) TO CLEAN BRUSH: remove vacuum shoe, tilt the machine on its right side, and hose off the brushes.

WINDSOR



OPERATION

86372330




01) Install jets and brush.



02) Fill solution tank with extraction rinse or fresh water.



03) Make sure that the handle is in the upright position and adjust the brush height by pushing down on the vacuum shoe and turning the lever and castle nut. Start at level 2 and adjust accordingly as brush wears. If the breaker trips, back off on the pressure on the brush.



04) Make sure that all three prongs are on the main body of the cord. If one of the prongs is missing, notify your supervisor immediately. Plug in to outlet and machine and twist to lock.



05) Pull lever to release brush deck and turn vacuum on and turn brush on.



06) Choose speed. Use slower speeds for deeper cleaning and faster speeds for lighter cleaning.



07) Grab handle to engage the brush and solution.