T3058 RF Module P/N127502-6 Users Guide

DOCUMENT NO: 136576

REVISION:

DATE OF ISSUE: JULY 08, 2013



Technisonic Industries <u>Limited</u>

240 Traders Boulevard, Mississauga, Ontario L4Z 1W7 Tel: (905) 890-2113 Fax: (905) 890-5338 www.til.ca

This document contains designs and other information which are the property of Technisonic Industries Ltd. This document may not in whole or in part, be duplicated or disclosed or used for manufacture of the part disclosed herein, without the prior written permission of Technisonic Industries Ltd.

INTRODUCTION

The T3058 RF module is a Dual Band transceiver assembly that operates in 450-512 MHz and 764-870 MHz range. The T3058 RF module is a modified Motorola APX 7000 UHF LHI/700/800 MHz portable radio.

The outer casing, top controls, front display and keypad are removed. The RF chassis is slightly machined but all electronic circuits are unmodified from the original APX 7000 radio.

The transceiver is designed to be installed and operated in a Technisonic Multiband Airborne Radio TDFM 9000 platform. All external power and antenna connections are provided by the TDFM 9000 as well as controls are via the front panel and display from the TDFM 9000.

The RF module is capable of operating on Analog FM, Wide and Narrow and Project 25 Phase 1 conventional and P25 Trunked Phase 1 and 2 systems.




FIGURE 1: Overall view of the T3058 RF Module

NOTES

ESD CAUTION



This unit contains static sensitive devices. Wear a grounded wrist strap and/or conductive gloves when handling printed circuit boards.

FCC COMPLIANCE INFORMATION

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference and (2) this device must accept any interference received, including interference that may cause undesired operation.



WARNING: For compliance with FCC RF Exposure Requirements the mobile transmitter antenna installation shall comply with the following two conditions:

- 1. The transmitter antenna gain shall not exceed 3 dBi.
- 2. The transmitter antenna is required to be located outside of a vehicle and kept at a separation distance of 80 cm or more between the transmitter antenna of this device and persons during operation.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- —Reorient or relocate the receiving antenna.
- —Increase the separation between the equipment and receiver.
- —Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- —Consult the dealer or an experienced radio/TV technician for help.

TECHNICAL CHARACTERISTICS

<u>Specification</u> <u>Characteristic</u>

Model Designation: T3058

Physical Dimensions: Approx. (L) 5.77" x (W) 2.1" x (H) 0.95"

Operating Temperature Range: -30°C to +60°C

Power Requirement:

Voltage: 7.5 VDC ± 15%

Current: 300 mA minimum / 2.4A maximum

Audio Output Power: 500 mW into 600Ω

FCC ID: IMA-T3058

INDUSTRY CANADA: 120A-T3058

RF Output Power: 1 or 5 Watts (UHF HI)

1 or 2.5 Watts (700 MHz)

1 or 3 Watts (800 MHz)

Frequency Range

UHF HI Band: 450-512 MHz TX

450-512 MHz RX

700 MHz Band:

800 MHz Band:

764-775, 794-805 MHz TX

764-797 MHz RX

806-824, 851-869 MHz TX

851-870 RX

No. of channels per band: 2000 pre-programmable channels

Transmitter section	UHF HI	700/800 MHz
FM Hum and noise in dB (wideband):	-45	-48
Audio Distortion:	1%	1%
Frequency Stability in ppm:	±1.5	±1.5
Modulation Limiting:	Wide band	±5kHz
	Narrow band	±2.5kHz
Receiver section	UHF HI	700/800 MHz

Receiver section	UHF HI	700/800 MF
Sensitivity in uV:		
*Digital 1% BER (12.5kHz)	0.31	0.35
*Digital 5% BER (12.5kHz)	0.21	0.25
**Analog with 12dB SINAD	0.25	0.25
Selectivity in dB:		
25 kHz Channel	-78	-75
12.5 kHz Channel	-68	-65
Intermodulation * **	-80	-80

^{*}Measured in digital mode per TIA / EIA IS 102.CAAA under nominal conditions.

^{**} Measured in analog mode per TIA / EIA 603 under nominal conditions.

INSTALATION

The T3058 module should be installed in the TDFM 9000 in accordance with TIL document 126556 "TDFM-9000 FINAL ASSEMBLY SSP".

FCC ID LABELS

The T3058 RF module is a modified Motorola APX 7000. Part of the modification requires removal if the original Motorola FCC ID label. After all modifications are done the new Technisonic FCC/IC ID label is applied.





FIGURE 2: APX 7000 FCC ID (Left), Right T3058 Module with new FCC ID applied

The FCC/Industry Canada label is shown below. It is mounted on the top near the front of the module.




FIGURE 3: T3058 FCC/Industry Canada Label



FIGURE 4: FCC/Industry Canada Label placement on the T3058 Module

The T3058 is intended to be mounted in the TDFM 9000 chassis and is not visible. Therefore, a second label must be applied to the outside of the TDFM 9000 that contains the following text: "TDFM 9000 Multiband Transceiver. Contains Module: FCC ID IMA-T3058". In addition, external labeling for Industry Canada shall be applied to the TDFM 9000 to include the following text: "Contains IC: 120A-T3058".

WARNING AND DISCLAIMER

Changes or modifications not expressly approved by Technisonic Industries could void the user's authority to operate the equipment.

This manual is designed to provide information about the T3058 RF Module. Every effort has been made to make this manual as complete and accurate as possible.

WARRANTY INFORMATION

The Model T3058 Transceiver is under warranty for one year from date of purchase. Failed units caused by defective parts, or workmanship should be returned to:

Technisonic Industries Limited 240 Traders Boulevard Mississauga, Ontario L4Z 1W7

Tel: (905) 890-2113 Fax: (905) 890-5338