

TOYOTA

TOYOTA MOTOR CORPORATION

1, TOYOTA-CHO, TOYOTA, AICHI, 471-8571 (Head Office)
or 471-8572 (Research & Development Group) JAPAN
TEL: +81-565-28-2121

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Date: February 8, 2010

Subject: Compliance Statement in Car manual FCC ID:NI4TMIMB-3

Dear Sirs,

Our products with the above FCC ID codes are low-frequency transmitters. The products will have been installed in cars before they are placed into the market.

We hereby assure that the following caution statement as per CFR 47, Part 15, Paragraph 15.21 is included in the owner's manuals of the cars:

The title "CAUTION TO USERS" or "FCC WARNING:" "NOTE:" or relevant title and "Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment."

In addition, we also assure that the following statement is also included in the manual as per CFR 47, Part 15, Paragraph 15.19(a)(3):

This device complies with Part 15 of the FCC Rules.

Operation is subject to the following two conditions:

- 1) this device may not cause harmful interference, and
- 2) this device must accept any interference received, including interference that may cause undesired operation.

Yours sincerely,



Tetsuya Matsuo
Toyota Motor Corporation
Telephone Number: +81-565-94-1007
Fax Number: +81-565-94-1192