



Visteon Japan, Ltd.
Hiroshima Sangyo Bunka
Center 9F 16-35, Hijiyama-
honmachi, Minami-ku,
Hiroshima 732-0816
JAPAN
TEL: +81- 82- 250- 6600
FAX: +81- 82- 250- 6809

To: MAZDA motor company
3-1, Shinchu, Futatabi-cho, Aki-gun,
Hiroshima, 730-8670, JAPAN

Date: December 22, 2005

Dear Sirs

Our product TX41794 (FCC ID: KPU41794) is a keyless entry transmitter for vehicle usage. Since this product will be already installed in cars (as original equipment) when placed into the U.S. market, we must hereby request that the following caution statement per CFR 47, Part 15, Paragraph 15.21 will be added to the car manual.

The title "CAUTION TO USER" or "FCC WARNING:" "NOTE:" or relevant title and "Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment."

Per CFR 47, Part 15, Paragraph 15.19(a)(3) the following statement must be added to the car manual:

"This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation."

Yours Sincerely,

Chikashi Tagawa
Manager
Body, Security Products
EPD

Visteon Japan, Ltd.
Hiroshima, Sangyo Bunka Center 9F
16-35, Hijiyama-honmachi, Minami-ku,
Hiroshima 732-0816 Japan