

Upgrade Guide Supplement



EclipseHX

System Upgrade Guide

Supplement

for

Eclipse HX-Omega

Eclipse HX-Median

Eclipse HX-PiCo

Rev 12.0.0 Rev A

Document Reference

Clear-Com Eclipse HX System Upgrade Guide Supplement

PN: PUB-00008 Rev A

Legal Disclaimers

Copyright © 2020 HME Clear-Com Ltd.

All rights reserved.

Clear-Com, the Clear-Com logo, and Clear-Com Concert are trademarks or registered trademarks of HM Electronics, Inc.

The software described in this document is furnished under a license agreement and may be used only in accordance with the terms of the agreement.

The product described in this document is distributed under licenses restricting its use, copying, distribution, and decompilation/reverse engineering. No part of this document may be reproduced in any form by any means without prior written authorization of Clear-Com, an HME Company.

Clear-Com Offices are located in California, USA; Cambridge, UK; Montreal, Canada; and Beijing, China. Specific addresses and contact information can be found on Clear-Com's corporate website:

www.clearcom.com

Clear-Com Contacts

Americas and Asia-Pacific Headquarters

California, United States

Tel: +1.510.337.6600

Email: CustomerServicesUS@clearcom.com

Europe, Middle East, and Africa Headquarters

Cambridge, United Kingdom

Tel: +44 1223 815000

Email: SalesSupportEMEA@clearcom.com

Canada Office

Quebec, Canada

Tel: +1 (450) 653-9669

China Office

Beijing Representative Office

Beijing, P.R.China

Tel: +8610 65811360/65815577

Introduction

This guide covers upgrading the Eclipse Omega, Eclipse Median and Eclipse PiCo systems to Eclipse HX-Omega, Eclipse HX-Median and Eclipse HX-PiCo respectively.

Note: If you are upgrading your PiCo to an HX-PiCo please contact your Clear-Com representative to establish if your hardware is HX ready. If your PiCo hardware is not HX ready, then this is a factory only upgrade.

This **Eclipse HX-Omega** upgrade pack contains

- ECLIPSE HX 12.0.0 SYSTEM SOFTWARE & DOCUMENTATION USB – T12632-1J1
- ECLIPSE SYSTEM DRIVERS USB – T12632-1A1
- ECLIPSE HX 12.0.0 SYSTEM SOFTWARE & DOCUMENTATION DVD – T12889-1J1
- ECLIPSE SYSTEM DRIVERS DVD – T12889-1A1
- ECLIPSE HX DOOR – T10607-2
- ECLIPSE HX DOOR HINGE SCREWS x 4 – 280432Z
- ECLIPSE HX-OMEGA MASKING LABEL – 375G037
- ECLIPSE CPU CARD CODE EPROM x 2 – 795002Z
- 256MB SDRAM MODULE x 2 – 481508Z
- MVX16A H8 PROGRAMMING CABLE – CAB-MVX-48Z
- FREESPEAK TO PC DATA CABLE – PD4007Z
- THIS UPGRADE GUIDE SUPPLEMENT – PUB-00008

This **Eclipse HX-Median** upgrade pack contains

- ECLIPSE HX 12.0.0 SYSTEM SOFTWARE & DOCUMENTATION USB – T12632-1J1
- ECLIPSE SYSTEM DRIVERS USB – T12632-1A1
- ECLIPSE HX 12.0.0 SYSTEM SOFTWARE & DOCUMENTATION DVD – T12889-1J1
- ECLIPSE SYSTEM DRIVERS DVD – T12889-1A1
- ECLIPSE HX DOOR – T10607-2
- ECLIPSE HX DOOR HINGE SCREWS x 4 – 280432Z
- ECLIPSE HX-MEDIAN MASKING LABEL – 375G036
- ECLIPSE CPU CARD CODE EPROM x 2 – 795002Z
- 256MB SDRAM MODULE x 2 – 481508Z
- MVX16A H8 PROGRAMMING CABLE – CAB-MVX-48Z
- FREESPEAK TO PC DATA CABLE – PD4007Z
- THIS UPGRADE GUIDE SUPPLEMENT – PUB-00008

This **Eclipse HX-PiCo** upgrade pack contains

- ECLIPSE HX 12.0.0 SYSTEM SOFTWARE & DOCUMENTATION USB – T12632-1J1
- ECLIPSE SYSTEM DRIVERS USB – T12632-1A1
- ECLIPSE HX 12.0.0 SYSTEM SOFTWARE & DOCUMENTATION DVD – T12889-1J1
- ECLIPSE SYSTEM DRIVERS DVD – T12889-1A1
- ECLIPSE HX-PICO MASKING LABEL – 375G038
- ECLIPSE PICO BOOT EPROM x 1 – 795014Z
- 256MB SDRAM MODULE x 1 – 481508Z
- MVX16A H8 PROGRAMMING CABLE – CAB-MVX-48Z
- FREESPEAK TO PC DATA CABLE – PD4007Z
- THIS UPGRADE GUIDE SUPPLEMENT – PUB-00008

PLEASE NOTE: ALL CHANGES ARE MADE WITH REFERENCE TO THE ECLIPSE HX UPGRADE GUIDE – P/N PUB-00007 – WHICH CAN BE FOUND ON THE ECLIPSE HX SYSTEM SOFTWARE AND DOCUMENTATION USB AND DVD

Note:

This upgrade requires a competent engineer. Specialist tools and additional cables may be required which are not supplied – see the Eclipse HX Upgrade Guide.

If there are any issues, please contact your local Clear-Com support office.

ECLIPSE HX-OMEGA and HX-MEDIAN UPGRADE STEPS

Carry out the following steps to upgrade your system

- Install EHx on your PC
- Install the door
- Apply the masking label to the back of the unit completely covering
 - “ECLIPSE OMEGA” with “ECLIPSE HX-OMEGA” or
 - “ECLIPSE MEDIAN” with “ECLIPSE HX-MEDIAN” or
- Change the CPU Card(s) PROM
- Change the CPU Card(s) RAM
- Change the CPU Card(s) DIP switches to set the Matrix type
- Upgrade the CPU Card(s) application Code
- Upgrade the CPU Card(s) CPLD code
- Upgrade the MVX, IVC, E-QUE, LMC, E-FIB cards application and FPGA code as appropriate
- Upgrade the V-Series panels using the TFTP method
- Upgrade the I-Station panels using the EHx method

ECLIPSE HX-PICO UPGRADE STEPS

Note: If you are upgrading your PiCo to an HX-PiCo please contact your Clear-Com representative to establish if your hardware is HX ready. If your PiCo hardware is not HX ready, then this is a factory only upgrade.

Carry out the following steps to upgrade your system

- Install EHX on your PC
- Apply the masking label to the back of the unit completely covering
 - “ECLIPSE PICO” with “ECLIPSE HX-PICO”
- Change the Eclipse HX-PiCo PROM
- Upgrade the Eclipse HX-PiCo RAM
- Change the Eclipse HX-PiCo DIP switches to set the Matrix type
- Upgrade the Eclipse HX-PiCo application Code
- Upgrade the Eclipse HX-PiCo MVX boot and/or application code
- Upgrade the V-Series panels using the TFTP method
- Upgrade the I-Station panels using the EHX method

For Reference:

The software /firmware components for Eclipse HX-Omega / HX-Median / HX-PiCo are listed in [Appendix A](#) below.

The documentation for Eclipse HX-Omega / HX-Median / HX-PiCo is listed in [Appendix B](#) below.

Tip: User documentation for all Eclipse products and EHX is available on the ECLIPSE HX 12.0.0 SYSTEM SOFTWARE & DOCUMENTATION USB and DVD, and from the Clear-Com website at: <http://www.clearcom.com/support>.

Note:

This upgrade requires a competent engineer. Specialist tools and additional cables may be required which are not supplied – see the Eclipse HX Upgrade Guide.

If there are any issues, please contact your local Clear-Com support office.

Appendix A: Eclipse HX Omega / Median / Delta / PiCo v12.0.0 Rev A Software Components

| | | | | | |
|------------|------------|-------|------------|------------|-------|
| USB | | | DVD | | |
| S/W | T12632-1J1 | Rev A | S/W | T12889-1J1 | Rev A |
| F/W | T12632-1A1 | Rev T | F/W | T12889-1A1 | Rev K |
| Doc | T12632-1J2 | Rev A | Doc | T12889-1J2 | Rev A |

| | Part No | Description | Device | File Type | C/Sum | Rev | Issue | Last updated |
|---------|---------|--|-----------------|------------|------------|-------|----------|--------------|
| Drivers | 710801Z | 4216 Custom Interface panel (V3 Release) | | S Record | E400H | B | BDH54M | Pre v4.2 |
| Drivers | 790016Z | 4222E BBH54P APP CODE, 2RU 32 PB ID | NA | 4kp | FFDE452E | A | BBH54P | v5.2.4 |
| Drivers | 790017Z | 4222E COAX BBG54P APP CODE, 2RU 32 PB ID | | 4kp | FFE762DF | A | BBG54P | v5.2.4 |
| Drivers | 710703Z | 4222E/4212E Panel Boot Code | | S | n/a | A | BR_60E | Pre v4.2 |
| Drivers | 710799Z | 4222E/4212E Panel Boot Code (Unloaded) | | S | n/a | A | BR_70G | Pre v4.2 |
| Drivers | 710847Z | 4224E/4226E/4294E/4215E Coax Panel | | 4kp | FFE5EF43 | 1 / A | PBG54M | Pre v4.2 |
| Drivers | 710705Z | 4224E/4226E/4294E/4215E Panel Boot Code | | S | n/a | A | PR_60E | Pre v4.2 |
| Drivers | 710800Z | 4224E/4226E/4294E/4215E Panel Boot Code (Unloaded) | | S | n/a | A | PR_70G | Pre v4.2 |
| Drivers | 710704Z | 4224E/4226E/4294E/4215E Panel Code | NA | 4kp | FFDB8081 | C | PBH54M | Pre v4.2 |
| Drivers | 710802Z | 4230 Vertical Extension panel (V3 Release) | | MOT | NA | A | HDH10H | Pre v4.2 |
| Drivers | 710813Z | AES-6 Application Code | AES-6 (710785Z) | MOT | n/a | 3 / C | 2.02 | v5.2.2 |
| Drivers | 710814Z | AES-6 XILINX Code | AES-6 (710785Z) | MCS | 0x010c84be | H | H | V7.6.0B |
| Drivers | 710858Z | AES-6-3K Xilinx Firmware | AES-6 (710785Z) | MCS | FFB55407 | 2 / B | 2 | v5.1.1 |
| Drivers | 790001Z | Config Card Boot EPROM Code Omega & Median Eclipse | ST 27W201 | S Record | 5468 | B | 2.4.22 | v7.0.0 A |
| Drivers | 710622Z | Config Card U1 CPLD Code | XC9572 | JED | 681F | D | 0.4.21.0 | v7.1.0 A |
| Drivers | 710623Z | Config Card U53 CPLD Code | XC95144 | JED | 330F | B | 0.2.27.0 | v7.1.0 A |
| Drivers | 710624Z | Config Rear Card CPLD Code | XC9572 | JED | 9411 | 4 / D | C | Pre v4.2 |
| Drivers | 710632Z | ICS-1016/1008 STATION CODE | | .4KP, .BIN | A865 | 4 / D | 010112 | Pre v4.2 |
| Drivers | 710644Z | DIG-2 Front Card Application Code | | S19 | n/a | 1 / A | B | Pre v4.2 |

| | Part No | Description | Device | File Type | C/Sum | Rev | Issue | Last updated |
|----------------|----------------|--|---------------|------------------|------------|----------|--|-----------------|
| Drivers | 710906Z | DIG-2 Front Card CPLD Code | Lattice 1016E | JED | 0C8A | 1 / A | A | Pre v4.2 |
| Drivers | 710643Z | DIG-2 Rear Card CPLD (U8) Code | XC95288XL | JED | 3.50E+08 | 1 / A | A | Pre v4.2 |
| Drivers | 710633Z | Eclipse 32 Boot PROM Code | | S Record | 3294 | E | 2.4.23 | v7.0.0 A |
| Drivers | 710659Z | Eclipse 32 FPGA Code | XCF04 | MCS | 0119AA3 | E | 1.5.19 | v7.0.0 A |
| Drivers | 710660Z | Eclipse 32 Glue Logic CPLD | XC9572 | JED | AB52 | E | E | v7.0.0 A |
| Drivers | 710661Z | Eclipse 32 GPIO Logic | XC95144 | JED | 6417 | 2 / B | B | Pre v4.2 |
| Drivers | 710848Z | Eclipse Serial Config Uploader | | .EXE | n/a | 1 / A | 2.0.1 | Pre v4.2 |
| Drivers | 710833Z | Eclipse Serial Number Generator | | .EXE | n/a | 1 / A | 1.0.0.0 | Pre v4.2 |
| Drivers | 780G037 | E-DANTE64-HX H8 FPGA | | .fwc | 0x149f629c | C | 1.2.59.0 | v10.0.0B |
| Drivers | 780G043 | E-DANTE64-HX H8 DSP | | .fwc | n/a | A | 1.4.60.0 | v8.8.0A |
| Drivers | 780G048 | E-DANTE64-HX BROOKLYN FPGA/APP/CFG Combined | | .dnt | n/a | C | BKLYN App 4.2.0.28 BKLYN FPGA 4.0.2.11 CC App 1.3.61.0 Config 1.4.0 | v12.0.0A |
| Drivers | 780G050 | E-DANTE64-HX H8 APP & BOOT Combined | | .mot | n/a | B | H8 APP 0.36.58.0 H8 BOOT 0.27.57.0 | v12.0.0A |
| Drivers | 710794Z | E-Fibre Networking (Rear) FPGA | | MCS | 010f82f5c | 4 / D | 1.23 | v5.1.1 |
| Drivers | 710793Z | E-Fibre Router (Front) FPGA | | MCS | 010f73f00 | 4 / D | 1.21 | v5.1.1 |
| Drivers | 790011Z | E-MADI CARD APP | | | n/a | C | 0.23.9.0 | V9.1.0A |
| Drivers | 790010Z | E-MADI CARD BOOT | | | n/a | B | 0.20.8.0 | V9.1.0A |
| Drivers | 790012Z | E-MADI CARD DSP | | | n/a | A | 1.4.11 | v5.2.4 |
| Drivers | 790009Z | E-MADI CARD FPGA | | | 0x16faba7e | F | 1.13.12.0 | v10.0.0D |
| Drivers | 780G041 | F/W, E-MADI MK-II FPGA | | MCS, SVF, FWC | 0x169b804c | E | 2.6.62.0 | v10.0.0D |
| Drivers | 780G052 | F/W, E-MADI MK-II BOOT/APP COMBO | | | | A | Boot 0.20.8.0 and App 0.23.9.0 | V9.1.0A |
| Drivers | 710810Z | E-Que Boot ROM Code | | SREC | DBB8 | 2 / B | 1.4 | v5.0.3 |

| | Part No | Description | Device | File Type | C/Sum | Rev | Issue | Last updated |
|----------------|----------------|---|--------------------|--------------------|------------|----------|--|-----------------|
| Drivers | 790006Z | E-QUE MK-II FPGA | | MCS, SVF | 0x119ef9f8 | C | 1.5.17.0 | v10.0.0A |
| Drivers | 710807Z | E-QUE MK-I FPGA | XCF16PVO48 C | MCS, SVF | 0x11a2d405 | J | 0.25.16.0 | v10.0.0A |
| Drivers | 785G053 | S/W. E-QUE APP MK-I & MK-II ECLIPSE | | .IMAGE | n/a | E | 7.29.5.0 | v8.7.0A |
| Drivers | 790004Z | E-Que MK-II Boot ROM Code | | BIN | n/a | A | 1.8.13 | v5.2.4 |
| Drivers | 710582Z | E-Station Flash code | MMC2107-144 | S19 | B2AB | A | 2.3 | Pre v4.2 |
| Drivers | 710581Z | E-Station Micro-P Boot Code | MMC2107-144 | S19 | FD2D | A | 2.3 | Pre v4.2 |
| Drivers | 780G004 | FS II 1.9 ANTENNA APPLICATION FIRMWARE | | FWW,FWS | n/a | H | 2.7.28.0 | v12.0.0A |
| Drivers | 780G003 | FS II 1.9 BELTPACK APPLICATION FIRMWARE | | FWW,FWS | n/a | R | 2.32.32.0 | v12.0.0A |
| Drivers | 780G065 | FSII IP 1.9 TRANSCEIVER RELEASE APPLICATION FIRMWARE | | .tar.gz | n/a | J | App 3.30.67.0 Boot 1.0.68.5 Baseband 0107 FPGA v.0.6.2- b44;v.2.3.2-b103-c4 | v12.0.0A |
| Drivers | 780G026 | FS II 2.4 ANTENNA FIRMWARE | | FWW,FWS | n/a | C | 2.2.49.0 | v11.1.0A |
| Drivers | 780G025 | FS II 2.4 BELTPACK APPLICATION FIRMWARE | | FWW,FWU,FWS | n/a | K | 2.28.50.0 | v12.0.0A |
| Drivers | 780G058 | E-IPA-HX APPLICATION FIRMWARE | | .tar.gz | n/a | L | App 3.100.63.0 FPGA 17.2.64.0 (v.2.0.0b6) Boot 2.0.65.03 | v12.0.0A |
| Drivers | 710907Z | FSBP CellCom / FreeSpeak Antenna and Beltpack bootloader | | .MOT | n/a | A | 1a | Pre v4.2 |
| Drivers | 790008Z | FSBP DECT STACK FS-BPJ, FREESPEAK | | .HEX | n/a | A | c6983_dect_hw_pp_ V26_K19 | v5.2.4 |
| Drivers | 710831Z | FSBP FreeSpeak Beltpack RM5 DECT Stack | | .HEX | n/a | 2 / B | c6657_dect_hw_pp_ v22_rm5 | Pre v4.2 |
| Drivers | 710828Z | FSBP MK I KIRK 6 Page BP App | | .MOT | n/a | R | 2K000279 | V8.5.2A |
| Drivers | 710827Z | FSBP MK II – Kirk Module – App Code | | .MOT | n/a | R | 3K010279 | V8.5.2A |
| Drivers | 710830Z | FSBP MK II – Kirk Module – DECT Code | | .HEX | n/a | 1 / A | C6983_dect_hw_pp_ v22_k19 | Pre v4.2 |
| Drivers | 710615Z | ICS-2003 Front Panel VFD Firmware | 18F242 | HEX | 104 | B | 1.1 | Pre v4.2 |
| Drivers | 710451Z | ICS-2003TE FPGA DNIC FRAMER COM-20 DIGITAL 2-WIRE COM. MODULE | QL2007- OPF144C | CHP, RPT | 5270DC | A | A | Pre v4.2 |

| | Part No | Description | Device | File Type | C/Sum | Rev | Issue | Last updated |
|---------|---------|---|----------------------|-------------|--|-------|------------------------------|--------------|
| Drivers | 710537Z | IMF-3 Backplane PIC Firmware | PIC16F505 | HEX | 88F8 | B | 1.2 | Pre v4.2 |
| Drivers | 785G045 | i-Station APP Code, Eclipse | N/A | FWP | n/a | C | 020901 | v9.0.0A |
| Drivers | 710663Z | i-Station Expansion Panel Code (e-Station) | NA | 4kp/Hex/s19 | FF9DBCAD | C | 10116 | v8.5.0A |
| Drivers | 710652Z | i-Station I-1100 CPLD | EPM3032ATC 44-10N | POF | 72059 | A | 1 | Pre v4.2 |
| Drivers | 710544Z | i-Station Master Station Flash code | 29LV200 | S19 | 477C | D | 2.3.9 | Pre v4.2 |
| Drivers | 780G018 | i-Station Micro-C Boot Code | MMC2107-144 | S19 | n/a | A | 6 | v8.0.0A |
| Drivers | 710547Z | i-Station PCI Code | PIC17C752 | HEX | 228A | A | A | Pre v4.2 |
| Drivers | 780G012 | MVX-HX APP Eclipse Omega/Median & Pico | | FWC | n/a | | 2.59.7.0 | V10.0.0D |
| Drivers | 780G015 | MVX-HX BOOT Eclipse Omega/Median & Pico | | FWC, MOT | n/a | A | 2.57.6.0 | V10.0.0D |
| Drivers | 780G011 | MVX-HX Combined BOOT & APP H8 FLASH, ECLIPSE & PICO | | BIN, MOT | n/a | B | 2.59.7.0 & 2.57.6.0 | V10.0.0D |
| Drivers | 710625Z | MVX-HX MK-I FPGA PROM CODE ECLIPSE | XC18V04 | MCS | 031F12B9 | J | 1.2.18 | v7.0.0 A |
| Drivers | 780G010 | MVX-HX MK-II FPGA FLASH MVXMK2 | | .MCS | MCS 0x33dbeb7a Flash 0x004ad7e9 | C | 2.9.47.0 | v8.7.0A |
| Drivers | 710824Z | PD2201 Active Antenna RM5 Application | | .MOT | n/a | 2 / B | AA_AR0020i | Pre v4.2 |
| Drivers | 710826Z | PD2201 Active Antenna RM5 DECT Stack | | .HEX | n/a | 2 / B | c6657_hw_fp_v21_r m5 | Pre v4.2 |
| Drivers | 710823Z | PD2201 Antenna - KIRK ACTIVE ANTENNA APP | | .MOT | n/a | A | AA_AK000206 | V7.6.0A |
| Drivers | 710825Z | PD2201 Antenna – Kirk Module – DECT Code | | .HEX | n/a | 1 / A | c6983_dect_hw_fp_ v21_k19 | Pre v4.2 |
| Drivers | 790007Z | PD2201 DECT STACK PD2201J, FREESPEAK | | .HEX | n/a | A | c6983_dect_hw_fp_ V26_K19 | v5.2.4 |
| Drivers | 710836Z | PD2202 RM5 - 1-6 Page Beltpack App | | .MOT | n/a | 8 / J | 1R010215 | v5.2.2 |

| | Part No | Description | Device | File Type | C/Sum | Rev | Issue | Last updated |
|-----------------|------------------|--|----------|----------------------------|------------|----------|--|-----------------|
| Drivers | 710853Z | PD2202/FS BP I RM5 6 Page BP App | | .MOT | n/a | 7 / H | 2R010215 | v5.2.2 |
| Drivers | 710829Z | PD2203 Antenna Splitter Application | | .MOT | n/a | 1 / A | SP0x010C | Pre v4.2 |
| Apple Store | 785G061 | S/W AGENT-IC IOS MOBILE CLIENT | | | n/a | C | 1.2 | v8.5.2A |
| Drivers | 785G089 | S/W, HX & ECLIPSE F/W USB IMAGE | | .ZIP | n/a | T | T | v12.0.0A |
| Doc | SOF-00015 | S/W, HX 12.0 DOC IMAGE USB DVD ECLIPSE HX | | .ZIP | n/a | A | A | v12.0.0A |
| Software | SOF-00016 | S/W, HX 12.0 SW IMAGE USB DVD ECLIPSE HX | | .ZIP | n/a | A | A | v12.0.0A |
| Software | SOF-00018 | S/W, HX 12.0 CFG CARD APP OMEGA, MEDIAN, DELTA ECLIPSE HX | | FWR | n/a | A | 22.59.2.0 | v12.0.0A |
| Software | 780G063 | F/W CONFIG CARD SECONDARY BOOT CODE | | FWR | n/a | A | 18.76.71.0 | v10.0.0A |
| Software | SOF-00014 | S/W, HX 12.0 EHX CONFIG ECLIPSE HX | | Exe | n/a | A | 22.64.1.0 | v12.0.0A |
| Software | SOF-00017 | S/W, HX 12.0 DYNAM-EC ECLIPSE HX | | .EXE | n/a | A | 17.8.4.0 | v12.0.0A |
| Software | SOF-00020 | S/W, HX 12.0, INSTALLER EHX & DYNAM-EC ECLIPSE HX | | .EXE | n/a | A | 1.0 EHX 22.64.1.0 Dynam-EC 17.8.4.0 | v12.0.0A |
| Software | SOF-00019 | S/W, HX 12.0, PICO APP ECLIPSE HX | | FWR | n/a | A | 22.59.3.0 | v12.0.0A |
| Software | 780G064 | F/W PiCo SECONDARY BOOT CODE | | FWR | n/a | A | 18.76.72.0 | v10.0.0A |
| Drivers | 750123Z | S/W, v1.1.14.0, DONGLE GENERATOR, ECLIPSE | | .EXE | n/a | A | V1.1.14.0 | v5.2.3 |
| Drivers | 710756Z | TEL-14 PROC. ADAPT. APPLICATION S/W | 89LPC935 | HEX | NA | 2 / B | 1.1 | Pre v4.2 |
| Drivers | 710657Z | TW-60 Firmware | 18F442 | HEX | 8F81 | B | 1 | Pre v4.2 |
| Drivers | 785G046 | V-Series V-PANEL APP, ECLIPSE | | FWP, JFFS2, 4KR | n/a | K | 4.11.0 | v12.0.0A |
| Drivers | 790039Z | V-Series Panel Display PIC Application Code, V-Series | | HEX,FWP,4K P | n/a | D | 0.48 | v9.1.0A |
| Drivers | 710815Z | V-Series Panel Display PIC Boot Loader Code | | 4KP, HEX, FWP | n/a | 3 / C | 2 | v5.1.3 |
| Drivers | 780G014 | V-Series Panel Kernel, V Series | | vmlImage | n/a | B | 2.6.24 | v9.0.0A |
| Drivers | 780G013 | V-Series Root File System, V Series | | rootfs.cramfs | n/a | B | Dec_19_16 | v9.0.0A |
| Drivers | 710859Z | V-Series T-Adapter Card Firmware | | .LDR | n/a | 1 / A | 1 | v5.1.1 |
| Drivers | 710817Z | V-Series UBOOT TFTP IMAGE | | LDR | n/a | I | 0.31 | V10.0.0D |
| Drivers | 785G125 | V-Iris-Series Main Application | | tar.gz | n/a | H | App 2.30.73.0 | v12.0.0A |

| | Part No | Description | Device | File Type | C/Sum | Rev | Issue | Last updated |
|---------|-----------|--|--------|-----------|-------|-----|--|--------------|
| | | | | | | | FPGA v.0.6.2-b44; v.2.3.2-b103-c4 UBoot 0.3.74.21 Kernel 4.4.32.0 Module App 1.4.81.0 | |
| Drivers | 780G067 | F/W, V-SERIES-IRIS 1.0 DISPLAY BOOTLOADER | | .elf | n/a | A | 0.0.82.5 | v11.0.0A |
| Drivers | SOF-00004 | F/W, FS EDGE BELTPACK APPLICATION FIRMWARE | | tar.gz | n/a | A | App 1.39.79.0 Boot 1.1.80.0 Baseband 0046-0046 | v12.0.0A |
| Drivers | 780G071 | F/W, FS EDGE TCVR APPLICATION FIRMWARE | | tar.gz | n/a | C | App 1.35.77.0 Boot 1.0.78.1 FPGA v.0.6.2b44; v.2.3.2-b103-c3 Baseband 0046-0046-0030-0030 | v12.0.0A |

Appendix C: Eclipse HX Omega / Median / PiCo v12.0.0 Rev A Documentation

- Note: All documentation is on the ECLIPSE HX 12.0.0 SYSTEM SOFTWARE & DOCUMENTATION USB and DVD

| | | | | | |
|------------|-------------------|--------------|------------|-------------------|--------------|
| USB | | | DVD | | |
| Doc | T12632-1J2 | Rev A | Doc | T12889-1J2 | Rev A |

| Part No | Description | Rev | Doc | Last |
|---------|--|-------|-----|----------|
| 810268Z | IFB-104 Interface Manual | 2 / B | 2 | v5.1.1 |
| 810291Z | FIM-108 Matrix Fibre Interface Instruction Manual | 1 / A | A | Pre v4.2 |
| 810306Z | FOR-22 Dual 4-Wire Interface Instruction Manual | 3 / C | 3 | v4.2 |
| 810307Z | CCI-22 Dual Party-Line Interface Instruction Manual | 3 / C | 3 | v4.2 |
| 810308Z | TEL-14 2-Channel Telephone Interface Instruction Manual | 3 / C | 3 | Pre v4.2 |
| 810309Z | GPI-6 General Purpose Inputs Interface Instruction Manual | 3 / C | 3 | Pre v4.2 |
| 810310Z | RLY-6 Relay Interface Instruction Manual | 3 / C | 3 | Pre v4.2 |
| 810311Z | DIF-102 / DIG-2 Digital interface Instruction Manual | 2 / B | 2 | v4.2 |
| 810313Z | Interface Module Frames: IMF-3, IMF-102, DIF102 Instruction Manual | 3 / C | 3 | Pre v4.2 |
| 810319Z | FIM-102D Matrix Fibre Interface Instruction Manual | 1 / A | A | Pre v4.2 |
| 810372Z | CellCom / FreeSpeak Wireless System Upgrade Manual | J | J | v5.2.4 |
| 810376Z | Eclipse Wireless Beltpack manual | 4 / D | 4 | v5.1.3 |
| 810383Z | AES-6 Interface Instruction Manual | 2 / B | 2 | v5.0.1 |
| 810385Z | FIM-202D Matrix Fibre Interface Instruction Manual | 3 / C | 3 | v5.1.1 |
| 810385Z | FIM-202D INSTRUCTION MANUAL | 3 / C | 3 | v5.1.1 |
| 810388Z | V-SERIES PANELS AES3 OPTN INST MANUAL | 3 / C | 3 | v5.1.1 |
| 810396Z | V-SERIES PANELS Rack-Mount LEVER KEY REFERENCE CARD | 2 / B | 2 | v5.1.1 |
| 810397Z | V-SERIES PANELS PUSH KEY REFERENCE CARD | 2 / B | 2 | v5.1.1 |
| 810398Z | V-SERIES PANELS DESKTOP REFERENCE CARD | 2 / B | 2 | v5.1.1 |
| 810403Z | BAL-8 Transformer Ground Isolation Interface Manual | 1 / A | 1 | v4.2 |
| 810405Z | V-SERIES PANELS XLR4M TO XLR7M UPGD MANUAL | C | C | v7.5.0A |
| 810406Z | V-SERIES PANELS T OPTN INST MANUAL | 1 / A | 1 | v5.1.1 |
| 810412Z | Active Antenna Synchronization Procedure | 1 / A | 1 | v5.1.1 |
| 810512Z | V-Series panels Desktop Push Button Reference Card | 1 / A | 1 | v5.1.1 |

| Part No | Description | Rev | Doc | Last |
|------------------|---|-----------|-----------|-----------------|
| 399G008 | INSTR, F/W RELEASE NOTE ECLIPSE | AD | AD | v12.0.0A |
| 399G035 | Eclipse HX-Delta Safety Instructions | A | A | v7.1.0 A |
| 399G046 | Eclipse HX Safety Instructions | A | A | v7.1.0 A |
| 399G050 | Eclipse HX-Delta PSU Bracket Mounting Instructions | A | A | v7.1.0 |
| 399G087 | GUIDE, FS II v1.0.0 USER | A | A | v7.6.0A |
| 399G106 | GUIDE, QSG SYSTEM, FS II V1.0.0 | A | A | v7.6.0A |
| 399G107 | GUIDE, QSG BELTPACK FS II V1.0.0 | A | A | v7.6.0A |
| 399G108 | GUIDE, QSG CHARGER, FS II V1.0.0 | A | A | v7.6.0A |
| 399G109 | GUIDE, QSG ANTENNA, FS II V1.0.0 | A | A | v7.6.0A |
| 399G304 | GUIDE, HX 12.0.0 WIRELESS USR ECLIPSE HX | B | B | v12.0.0A |
| 399G265 | GUIDE, HX 10.0.0 DYNAM-EC QSG ECLIPSE HX | A | A | v10.0.0A |
| 399G207 | GUIDE, HX 9.0.0 I-PNL USR ECLIPSE HX | A | A | v9.0.0A |
| 399G299 | GUIDE, HX 11.1.0 PICO USER ECLIPSE HX | A | A | v11.1.0A |
| 399G264 | GUIDE, HX 12.0.0 DYNAM-EC USR ECLIPSE HX | B | B | v12.0.0A |
| PUB-00003 | GUIDE, HX 12.0 CONFIG SW ECLIPSE HX | A | A | v12.0.0A |
| 399G301 | GUIDE, HX 12.0.0 V-PNL USR ECLIPSE HX | B | B | v12.0.0A |
| PUB-00007 | GUIDE, HX 12.0 UPGRADE ECLIPSE HX | A | A | v12.0.0A |
| PUB-00005 | GUIDE, HX 12.0 OMEGA USR ECLIPSE HX | A | A | v12.0.0A |
| PUB-00006 | GUIDE, HX 12.0 MEDIAN USR ECLIPSE HX | A | A | v12.0.0A |
| PUB-00004 | GUIDE, HX 12.0. DELTA USR ECLIPSE HX | A | A | v12.0.0A |
| 399G303 | GUIDE, HX 11.1.0 FRAME INST ECLIPSE HX | A | A | v11.1.0A |
| PUB-00008 | GUIDE, HX 12.0.0 UG SUPP ECLIPSE HX | A | A | v12.0.0A |
| PUB-00010 | NTE, HX 12.0 CUST REL ECLIPSE HX | A | A | v12.0.0A |
| 399G266 | GDE, HX 12.0.0 EHX LOGIC ECLIPSE HX | B | B | v12.0.0A |
| 399G158 | GDE, HX 8.5.0 ECLIPSE QSG ECLIPSE HX | A | A | v8.5.0A |
| 399G222 | GDE, HX 9.0.0 ICS 1008E/1016E, ECLIPSE HX | A | A | v9.0.0A |
| 399G223 | GDE, HX 9.0.0 ICS 22 SPKR PANEL, ECLIPSE HX | A | A | v9.0.0A |
| 399G250 | GUIDE, QSG IP TCVR, FS II | A | A | v10.0.0A |
| 399G250P | GUIDE, QSG IP TCVR, FS II (Portuguese) | A | A | v10.0.0A |
| 399G261 | QSG, E-IPA-HX LICENSING | A | A | v10.0.0A |
| PUB-00011 | GDE, AoIP NETWORK RECOMMENDATIONS GUIDE ECLIPSE HX | A | A | v12.0.0A |

| Part No | Description | Rev | Doc | Last |
|-----------|---|-----|-----|----------|
| PUB-00012 | INSTR, V-SERIES IRIS USER GUIDE | A | A | v12.0.0A |
| 399G279 | INSTR, V-SERIES SAFETY | B | B | v12.0.0A |
| 399G291 | INSTR, ECLIPSE HX SAFETY | B | B | v12.0.0A |
| 399G283 | NOTE. SW EULA, END USER LICENSING AGREEMENT | A | A | v11.0.0A |
| 399G303 | GUIDE, HX 11.1.0 FRAME INSTAL ECLIPSE HX | A | A | v11.1.0A |
| 399G322 | FreeSpeak Edge Battery Charger QSG | A | A | V12.0.0A |
| 399G326 | FreeSpeak Edge Beltpack QSG | B | B | V12.0.0A |
| 399G327 | FreeSpeak Edge Transceiver QSG | A | A | V12.0.0A |
| PUB-00020 | FS Edge User Guide | A | A | V12.0.0A |

