

How to upgrade the firmware for Tribit MAXSound Plus

1. Install the upgrade tool “Media product tool”.

Unzip the file as below, and double-click “setup” to install the upgrade tool “Media product tool”.

MSI	2018/11/27 16:04	WinRAR 压缩文件	30,202 KB
Msicn	2018/11/27 16:04	Windows Install...	363 KB
Msien	2018/11/27 16:04	Windows Install...	366 KB
Msitw	2018/11/27 16:04	Windows Install...	363 KB
setup	2017/5/18 13:59	应用程序	28 KB

The software interface as below,




2. Upgrade the firmware.

Step 1: Keep MAXSound Plus “power off”, Connect MAXSound Plus and PC use the Micro-USB Cable and follow the step as below:



Remark: Please use the USB Cable with data transmission function.


Step 2: Long press (>1S) “power” and “Volume +” button Simultaneously, and the upgrade tool will detect MAXSound Plus.



Step 3: Click this button to load the firmware file



Step 4: Find the folder of the firmware and double click
“CGBT1355_2825C_BT265(...)” file.



Step 5: Click here to finish the firmware adding.



Step 6: Click this button to begin the firmware upgrading.



Step 7: Upgrade successful.

