

Errata / Addendum

Low-Mid Density Mediant™ Series

Documentation Suite

Release 6.4

This document lists errata / addendum item(s)–corrections and/or additions–for AudioCodes SIP Mediant product line, containing significant information discovered after the release or too late in the release cycle to be otherwise included in the GA release documentation.

Information contained in this document is believed to be accurate and reliable at the time of printing. However, due to ongoing product improvements and revisions, AudioCodes cannot guarantee accuracy of printed material after the Date Published nor can it accept responsibility for errors or omissions. Updates to this document and other documents as well as software files can be downloaded by registered customers at <http://www.audiocodes.com/downloads>.

© Copyright 2012. AudioCodes Ltd. All rights reserved.
This document is subject to change without notice.

Document #: LTRT-29102

Document Revision Record

Rev. #	Date	Comment
-	April 16, 2012	Initial publication.

International Headquarters

1 Hayarden Street, Airport City, Lod 70151
P.O.Box 255, Ben Gurion Airport, Israel 70100
Tel: +972-3-976-4000 Fax: +972-3-976-4040

AudioCodes Inc.

27 World's Fair Drive, Somerset, NJ 08873
Tel:+1-732-469-0880 Fax:+1-732-496-2298

Contact:

www.audiocodes.com/info

Website:

www.audiocodes.com

Major Updates

The major updates that were made in the Release 6.4 documentation:

- The 3xxBehavior parameter description was modified.
- The EnableAutoRAITransmitBER parameter was moved to the section containing additional Remote Alarm Indication parameters.
- The EnableCallWaiting parameter description was modified.
- The IPGroup_EnableSurvivability parameter description was modified with the new option value, [3] Always Terminate Register.
- The chapter on LDAP queries was significantly modified.
- The IP Connectivity feature was modified.
- New sections on the Alternative Routing feature were added, facilitating understanding of this capability.
- PRT was removed from Mediant 800 series documents.
- The RTPOnlyMode parameter description was modified.
- The SBCEnableAASTRASurvivabilityNotice parameter was added to SBC devices.
- The SetDefaultLinePolarityState parameter was added to FXO devices.
- The ManipulateIP2PSTNReferTo parameter was added.
- The Note bulletin informing the user that the IP Group Type, "Gateway" can only be configured using the INI file was removed; it's now configurable through the Web.
- The Note bulletin informing the user that NW traces is currently not applicable to MSBG series devices was removed; it's now supported by these devices.
- The default value of the ISDNDisconnectOnBusyTone parameter was modified.
- The MediaChannels parameter description was modified.
- The description of the usage of apostrophe in the syntax for SIP message manipulation rules was modified.
- The section on FXO Device Interworking SIP E911 Calls from Service Provider's IP Network to PSAP DID Lines was updated with the SetDefaultLinePolarityState parameter.
- The UseSourceNumberAsDisplayName parameter was updated with the new option [3], and the description of the ReplaceCallingWithRedirectNumber parameter was modified accordingly.

International Headquarters

1 Hayarden Street, Airport City, Lod 70151
P.O.Box 255, Ben Gurion Airport, Israel 70100
Tel: +972-3-976-4000 Fax: +972-3-976-4040

AudioCodes Inc.

27 World's Fair Drive, Somerset, NJ 08873
Tel: +1-732-469-0880 Fax: +1-732-496-2298

Contact:

www.audiocodes.com/info

Website:

www.audiocodes.com

- The descriptions of the EnableISDNTunnelingIP2Tel and AddIEinSetup parameters were modified.
- The AltRoutingTel2IPMode parameter description was modified.
- The description of the CDR "Orig" field was modified.
- The PSTNExtendedParams parameter description was modified.
- The IPGroup_ContactName parameter was added.
- The NTEMaxDuration parameter description was modified.
- The mention of the IPMediaDspCh Feature Key was removed from the manual; this is installed by default.
- The L1L1ComplexTxUDPPort and L1L1ComplexRxUDPPort parameters were added; these were removed in an earlier release.
- Initial IP address assignment procedure was modified for E-SBC devices that mentioned embedded DHCP; embedded DHCP is supported only on MSBG series devices.
- E&M interface wiring for Type 5 was added to the Mediant 800 documents.
- Maximum capacity figures (e.g., SBC sessions) were removed from the manuals.
- A Note bulletin was added informing the user that ping is not supported on MSBG series devices.
- The description of the PlayRBTone2Trunk_ID and PlayRBTone2Tel parameters were modified.
- The section on Collecting DR Messages at Device Startup was modified.
- The DisableReminderRing parameter description was modified.
- The description of the NATTranslation table was modified.
- The Message Manipulation feature was updated with enhanced string comparisons using Booleans.
- The DisableCryptoLifeTimelinSDP parameter was added.
- The UseReferredByForCallingNumber parameter was added and the section Blind Call Transfer was updated accordingly.
- The TransferCapabilityForDataCalls parameter was added.
- The AddNPIandTON2RedirectNumber parameter was added.
- The MediaSecurityBehaviour parameter description was modified.
- The message manipulation feature, Message Manipulation using SDP Conditions was added.

International Headquarters

1 Hayarden Street, Airport City, Lod 70151
P.O.Box 255, Ben Gurion Airport, Israel 70100
Tel: +972-3-976-4000 Fax: +972-3-976-4040

AudioCodes Inc.

27 World's Fair Drive, Somerset, NJ 08873
Tel: +1-732-469-0880 Fax: +1-732-496-2298

Contact:

www.audiocodes.com/info

Website:

www.audiocodes.com

- The WatchdogStatus parameter was removed.
- The SRTPOfferedSuites parameter description was modified.
- Typo "G.771" was changed to "G.711".
- The default and port range of the WANMgmtSNMPPort parameter was added.
- The chapter on DSP resources was modified for Mediant 1000 series devices.
- The IP2IPTranscodingMode parameter description was modified.

International Headquarters

1 Hayarden Street, Airport City, Lod 70151
P.O.Box 255, Ben Gurion Airport, Israel 70100
Tel: +972-3-976-4000 Fax: +972-3-976-4040

AudioCodes Inc.

27 World's Fair Drive, Somerset, NJ 08873
Tel:+1-732-469-0880 Fax:+1-732-496-2298

Contact:

www.audiocodes.com/info

Website:

www.audiocodes.com