



IMPORTANT SAFETY RECALL

Inversion Therapy Table (Model No. 55-1531)
Pro Inversion System (Model Nos. 55-1536, 1536A and 1536B)



55-1531



55-1536 & 55-1536A



55-1536B

During exercise, the unit may break at a weld in the center of the Inversion Table causing a person to fall off the Inversion Table and possibly injure himself or herself.

The Inversion Tables have the name “Inversion Therapy Table” or “Pro Inversion System.”

Only Inversion Tables with the following serial numbers are part of this recall:

- “Inversion Therapy Table”: 05NOV000001 through 05NOV000414 and 05DEC000415 through 05DEC000828
- “Pro Inversion System”: 05SEP000001 through 05SEP000528; 06NOV000001 through 06NOV000528; and 07SEP000001 through 07SEP000528

If facing the front of the Inversion Table, the serial number is located on the black Stamina label that is to the left of the rubber stopper located on the cross bar.

If you have one of these Inversion Tables, **stop using it immediately** and contact Stamina Products at 888-STAMINA (888-782-6462). Stamina Products will arrange to pick up the Inversion Table and offer you a replacement or refund.

If you have any questions regarding this recall, you may call 888-STAMINA (888-782-6462).