

Morris Leslie

PLANT SALES

Morris Leslie Telehandler Inspection Form

Year:	2017	Serial Number:	2565886	Machine Code:	na			
Make:	jcb	Model:	535-125					
Fleet Number:	mlp7668	Registration Number:	WP17XT0					
Comments								
Hour Clock Working:	y	Machine Hours:	2369					
TYRES MUST BE MINIMUM 30% REMAINING								
Tyre Size:	15.5/80-24	N/S/F%:	90	O/S/F%:	90			
Gross Weight(kg):	10020	Lift Capacity (kg):	3500	Lift Height (m):	12			
Engine (kw/hp) :	55.4	Turbo:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	AdBlue:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Air Conditioning:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Sway Control:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Stabilisers:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Pallet Forks	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Fork Positioners	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	GP Shovel	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Controls (Lever/Joystick):	lever	EPA Approved:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO					
Hitch (Manual/Hydraulic):	man	4th Gear:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO					
Body Work Condition (Any Damage):	good							
Glass (Any Damage):	good	Mirrors:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO					
Road Lights:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Paintwork:	fair					
Ram Leaks or Damage:	nil							
Auxiliary Pipe Work:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO							
Double Acting:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO							
Any other Comments on Condition:								
Radio:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO							
Beacon:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO							
All Photos Attached (Total 10)	Left Side	<input checked="" type="checkbox"/>	Right Side	<input checked="" type="checkbox"/>	4x Corner	<input checked="" type="checkbox"/>	Serial Plate	<input checked="" type="checkbox"/>
	Hours Clock	<input checked="" type="checkbox"/>	Engine	<input checked="" type="checkbox"/>	Cab	<input checked="" type="checkbox"/>	Controls	<input checked="" type="checkbox"/>
	Engine Plate	<input checked="" type="checkbox"/>						
Date of Last Service:	13.12.19@2327hrs		Date Next Service Due:	@2800hrs				
Last Service Sheet Attached:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Current Loler attached:		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
SERVICE TO BE DONE BEFORE GOING TO SALES WITHIN 100HRS OF SERVICE DUE								
Service Records Supplied:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO							
Red Key with Machine with picture:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO							
Manufacturers Decals with Machine:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO							
Depot:	Bedford							
Inspected By:	scott	Date:	10.2.20					
To be signed off by Plant Sales:								
Inspected By:	Sam	Date:	10.2.20					